Proposed Draft

Serial ATA International Organization

Version 0.2
January 14, 2010

Serial ATA Revision 3.0 ECN # 041
Title : To correct SATA Internal 4 Lane Pin Assignments, Figure 44

This is an internal working document of the Serial ATA International Organization. As such, this is not a completed standard and has not been approved. The Serial ATA International Organization may modify the contents at any time. This document is made available for review and comment only.

Permission is granted to the Promoters, Contributors and Adopters of the Serial ATA International Organization to reproduce this document for the purposes of evolving the technical content for internal use only without further permission provided this notice is included. All other rights are reserved and may be covered by one or more Non Disclosure Agreements including the Serial ATA International Organization participant agreements. Any commercial or for-profit replication or republication is prohibited. Copyright © 2000-2009 Serial ATA International Organization. All rights reserved.

This Draft Specification is NOT the final version of the Specification and is subject to change without notice. A modified, final version of this Specification ("Final Specification") when approved by the Promoters will be made available for download at this Web Site: http://www.sata-io.org.

THIS DRAFT SPECIFICATION IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, NON-INFRINGEMENT, FITNESS FOR ANY PARTICULAR PURPOSE OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION, OR SAMPLE. Except for the right to download for internal review, no license, express or implied, by estopple or otherwise, to any intellectual property rights is granted or intended hereunder.

THE PROMOTERS DISCLAIM ALL LIABILITY, INCLUDING LIABILITY FOR INFRINGEMENT OF ANY PROPRIETARY RIGHTS, RELATING TO USE OF INFORMATION IN THIS DRAFT SPECIFICATION. THE PROMOTERS DO NOT WARRANT OR REPRESENT THAT SUCH USE WILL NOT INFRINGE SUCH RIGHTS.

THIS DOCUMENT IS AN INTERMEDIATE DRAFT FOR COMMENT ONLY AND IS SUBJECT TO CHANGE WITHOUT NOTICE.

* Other brands and names are the property of their respective owners.

Copyright © 2005-2009 Serial ATA International Organization. All rights reserved.

Author Information

Author Name	Company	Email address
Alvin Cox Frank Chu	Seagate Hitachi GST	Alvin.Cox@Seagate.com Frank.Chu@Hitachigst.com

Workgroup Chair Information

Workgroup	Chairperson Name	Email address
CabCon	Frank Chu	Frank.Chu@Hitachigst.com

Document History

Version	Date	Comments
0.1	01-14-2010	Initial draft
0.2	01-14-2010	Minor revision

1 Introduction

1.1 Problem Statement

To correct the wrong pin assignments in Section 6.1.11.2 Figure 44, 4 Lane Pin Assignments.

.

1.2 Solution Summary

Correction of the backplane pin assignment in the lower right of Figure 44.

2 Technical Specification Changes

2.1 <6.1.11.2 4 Lane Pin Assignments>

Replacing the old Figure 44



with the following new Figure 44: